

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES


**MICHAEL R. STYLER**  
Executive Director

### Division of Oil, Gas and Mining

**JOHN R. BAZA**  
Division Director

0002

### Inspection Report Minerals Regulatory Program October 14, 2009

Reviewed: 

<b>Mine Name:</b> Marblehead Mtn Processing	<b>Permit Number:</b> M/045/0024
<b>Operator Name:</b> Chemical Lime Company	<b>Inspection Date:</b> October 07, 2009
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 10:30:00 am
<b>Other Participants:</b> None	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 04-20-2009 **Bond Amount:** \$456,200 **Permit fee** is up to date

**Purpose of Inspection:** Routine annual Inspection. The Large Mine site was last inspected 03-25-2008.

**Inspection Summary:** Locked gate at entrance to the site. Buildings are actively being demolished, there is a noticeable change from last year. Product stockpiles are still on site. Area will need to be regraded and seeded. No new reclamation at the mine site.

See attached photos that were taken to document site conditions.

**Conclusions and Recommendations:** Bond is past due for escalation. OGM recommends that the Operator contacts the Division for a seed mix, and the area should be reseeded in the fall, after the area has been graded and the surface roughened. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature** 

LAH:vs

cc: Brett Wilson

SITLA - [Jblake@utah.gov](mailto:Jblake@utah.gov)

O:\M045-Tooele\M0450024-MarbleheadMtnProcessingPlant\inspections\Insp-10072009.doc



0002

